



JetMove 2xx
Version Update
from V. 2.01 to V. 2.02



Jetter AG reserves the right to make alterations to its products in the interest of technical progress. These alterations need not to be documented in every single case.

This manual and the information contained herein have been compiled with due diligence. Jetter AG shall not be liable for printing errors contained herein or for other consequential damage.

The brand names and product names used in this manual are trade marks or registered trade marks of the respective title owner.

Table of Contents

1	Introduction	4
2	Expansions	5
3	Corrections	5
3.1	Busy Bit:	5
3.2	Error F11	5

1 Introduction

Version Updates - Survey			
Version	Function	upgraded	corrected
V 2.00	in general	✓	
V 2.01	Motor temperature acquisition	✓	
	Error F15	✓	
	Change of rotation	✓	
	Register 199 Version number		✓
	Limit switch logic circuit		✓
V 2.02	Busy bit:		✓
	Error F11		✓

2 Expansions

3 Corrections

3.1 Busy Bit:

Up to this version, processing the motion instructions would occasionally come to a standstill due to a busy bit not having been set correctly.

3.2 Error F11

Up to this version, at a double rated current of the device, error F11 Current Overrange would occasionally occur without a reason.